MATERIAL SAFETY DATA SHEET

NPCA 1-

DPN 5075

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20) COMPONENT I E OF PREP

Section I

MANUFACTURER'S NAME

DEFT CHEMICAL COATINGS

STREET ADDRESS 17451 Von Karman Ave.

Irvine, CA 92714

EMERGENCY TELEPHONE NO.

714-549-8911

INFORMATION TELEPHONE NO.

PRODUCTCLASS: Epoxy Coating O1-Y-2 Base Component

Base Component, Gloss Yellow Epoxy

Section II — HAZ	ARDOUS	INGREDIE	ENTS 🗱 🞉	三种 副第二次	
INGREDIENT	PERCENT wt.	Y≘¥=0 T PPM	LV	LEL	VAPOR SERVE
Lt.Chrome Yellow Pigment Nethyl Ethyl Ketone N-Proply Acetate Toluene Isobutyl Acetate Thyl Cellosolve N-Butyl Alcohol Butyl Cellosolve	30 10 10 10 5 <5 <5 <5	200 200 100 150 25 100 50	0.05	NA 2.0 1.7 1.0 1.27 2.28 1.45 1.1	NA 70.0 23.0 22.0 12.5 6.2 4.4 1.0

Section III — PHYSICAL DATA

BOILING RANGE

 $175 - 340^{0}$ F

VAPOR DENSITY

X HEAVIER.

Estricture 20 EVAPORATION RATE

FASTER

X SLOWER, THAN ETHER

PERCENT VOLATILE 63.7% BY VOLUME -

WEIGHTPER GALLON

10.79

Section IV — FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION - Flammable Karana and L

280F Tag Open Cup

LEL

extinguishing MEDIA - Carbon dioxide, foam or dry chemicals.

INUSUAL FIRE AND EXPLOSION HAZARDS

- Caution against application to hot surfaces and use in areas where sparks or open flames may be present.

and the same of the same of the same

- Do not use water stream which might spread fire. Water spray or fog can be used effectively.

Section V — HEALTH HAZARD DATA
HRESHOLD LIMIT VALUE See Section II
Moderate eye irritant. Possible irritation of skin by solvent Irritation or narcosis can result from inhalation of solvent vapors. MERGENCY AND FIRST AID PROCEDURES Skin contact - wipe off with a rag then thorough rinsing with water and washing with mild soap and water. Eye contact - flush 10 minutes with water and consult eye physician. Inhalation - remove to fresh air.
Section VI — REACTIVITY DATA
CONDITIONS TO AVOID - Sparks from being struck with steel object or static electricity. Avoid open flam in vicinity. Avoid exposure to heat. AZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR. DATE OF THE PROPERTY OF THE P
Section VII — UPILL OR LEAK PROCEDURES
rags. Flush with large volume of water. Avoid sparks or open flame. Astedisposal Method - Dispose of clean-up rags by wetting with water and keep in a closed container. Dispose in tightly closed container and finally sanitary
Section VIII — SPECIAL PROTECTION INFORMATION landfill.
OTECTIVE GLOVES - Yes E PROTECTION - Yes HER PROTECTIVE EQUIPMENT
Section IX — SPECIAL PRECAUTIONS
Use normal storing precautions as with any paint. Keep away from heat, spark or open flame. HERPRECAUTIONS - Avoid prolonged inhalation of vapors.